

Responding to Reoccurring Coliform Detects South Shore Water System South Kingstown, RI

NEWWA Spring Conference & Exposition DCU Center, Worcester, MA April 1, 2015


Kristen Berger, P.E.
Comprehensive Environmental Inc.



Outline

- Introduction
- South Shore System
- Hydraulic Model
- Evaluation Overview
- Summary

South Kingstown






Introduction



Total Coliforms

- Total Coliforms
 - Gram-negative, aerobic or facultative anaerobic, nonspore forming rods

Coliform bacteria



- Include both harmless bacteria and pathogenic bacteria (fecal coliform)
- Fecal Coliforms are a type of Total Coliform
- E. coli are a type of Fecal Coliform



Revised Total Coliform Rule

- Initial TCR, 1989, developed to set goals for presence of TC and limits for FC or E. coli
- TC indicator for system integrity
- E. coli indicator of fecal coliform indicates contamination of water by warm-blooded animal
- RTCR, 2013, MCL for *E. coli* but not for TC
 - Level 1 Assessment
 - Required if more than 2 TC positives
 - Level 2 Assessment (by State or State approved party)
 - Second Level 1 trigger within rolling 12-month period or in 2 consecutive years



South Shore Water System






System Overview

- 2,479 accounts primarily residential with light commercial
- 0.35 MGD Average Day; 0.9 MGD Max Day
- 47 miles water main 4" to 14" mainly AC pipe
- Two 400,000 gallon elevated water storage tanks on opposite ends of system
- Booster pumping station
- Source since about 2003: Interconnection with United Water Rhode Island (UWRI)



South Shore TC Detects

- 5 Regular Monitoring Sites in South Shore Water System
- Detections occurred at the Mautucket Road Tank regular sample site
 - October 2, 4 and 11, 2012
 - May 21 and 23, 2013
 - o July 23 and 25, 2013
- Repeat samples taken in area of the tank were total coliform positive
- No E. coli





UWRI – South Kingstown


- Gravel packed wells (Tuckertown Road) about 2 miles from interconnection (Fe < 0.05 mg/L, Mn < 0.02 mg/L)
- Treatment at one of two facilities, both have:
 - Aeration for CO₂ removal,
 - Lime pH adjustment (8-14 mg/L),
 - Zinc orthophosphate corrosion control (2.5-3 mg/L)
 - Sodium hypochlorite disinfection (0.6-0.7 mg/L)
- Finished water pH is about 7.5
- Groundwater temperature 53°F winter to 58°F summer
- Total coliform positive detections have occurred (as recently as Nov 2013) repeat sampling TC absent.




South Shore - Distribution

- Victoria Lane Tank (East Zone)
 400,000 gal
- Mautucket Road Tank (West Zone) 400,000 gal
- Water main 4" 14" total
 755,000 gallons, primarily AC
 pipe, DI used for new pipes

1.6 MG Storage in Distribution System







Residual Chlorine

- Chlorinated water supplied by UWRI
- Town monitors twice monthly at several locations
- Level at interconnection typically
 0.3-0.5 mg/L, but can be < 0.1 mg/L
- Levels at TC sampling sites typically trace amounts
- Levels at Mautucket Road Tank site
 0.0 to 0.05 mg/L Essentially Non-Detect



Hydraulic Model




Model

- Developed using WaterCAD/GEMS
- Tanks with Operating Levels
- Interconnection with altitude valve controls and meter
- Booster Pumps
- Demands Average Day and Max Day
- Extended runs Diurnal Curve
- Water Age
- Residual Chlorine



Existing Conditions/Operations Water Age – Average Day





Existing Conditions/Operations Residual Chlorine





Chlorine Added at Booster PS

- Hourly Changing Average Day Demand
- Assumes 0.4 mg/L residual chlorine provided at interconnection and another 0.4 mg/L added at Booster Pump Station
- Over the two weeks modeled no improvement over the existing conditions.
- Areas near the Booster Pump Station experience levels up to 0.7 mg/L, which may cause complaints
- Validated by historical observations by Water Department staff when chlorine was added at Booster Pump Station in the past.




Chlorine Added at Mautucket Road Tank

- Hourly Changing Average Day Demand
- Assumes 0.4 mg/L residual chlorine provided at interconnection and another 0.4 mg/L added as water flows out of Mautucket Road Tank
- Over two weeks shown, residual chlorine remains close to 0.4 mg/L in the areas around Mautucket Road Tank. This is an improvement over existing conditions.
- No areas of the system are greater than
 0.4 mg/L chlorine



Chlorine Addition at Mautucket Road Tank






Evaluation Overview



Factors
Impacting
Total
Coliform
Detects





Sampling Protocol

- Samples taken by Water Department Staff
- Samples taken at each sample location in the same manner
 - If present, aerators are removed
 - Sample tap is disinfected
 - Sample tap flushed for several minutes
 - Sample taken, covered and stored for transport to lab
- Since detects reoccur in the same location (Mautucket Tank) and not at other sites the sampling protocol is not a likely cause of coliform detections




System Operations

- System operations that can cause disruptions
 - Main breaks
 - Main construction
 - Power losses
 - Pressure losses
 - Source water changes
 - Flushing and Changes in flow patterns
 - Flushing and/or tank level change did occur prior to detects



Tank Levels: Sep – Oct 2012

Water Levels in Water Storage Tanks





Flushing

- Flushing at lower velocities can exacerbate problems by disturbing/sloughing and mobilizing biofilms and sediment but not removing them
- Velocity
 - Conventional approach 2.5 fps minimum
 - 12-inch dia. main, 2.5 fps is about 900 gpm
 - More recent research shows the minimum velocity needed to remove sediment 5 fps
 - 12-inch dia. main, 5 fps is about 1800 gpm
- Helps explain why some systems see higher levels of coliforms after flushing



Evaluation Summary

- Sampling protocol Not likely factor
- System operations Likely contributing factor
- Climate conditions Warming air temperatures contribute to warming water temperature (precipitation not likely factor)
- Residence times Likely contributing factor
- Residual chlorine levels Likely contributing factor
- Nutrients Organics not a likely factor for this system however, materials of construction could contribute



Coliform Source

- Potential Sources of Coliform
 - Soil and Water Surrounding Pipes Possible source during main repair and construction
 - Biofilms Likely source
 - Difficult to pin point
 - Random sampling of pipe surfaces may not detect
 - Sediment in both pipes and tanks Likely source since velocities in mains are low
 - Corrosion tubercles Not likely since mostly AC pipe
 - Materials in Use Possible, materials could have been contaminated during installation
 - Customer Connections Possible, no current cross connection survey



Susceptible Locations/Times

- Dead-ends where residence times and water temperatures are highest
- Areas that are difficult to flush at high enough velocities
- Spring to Fall Higher water temperature
- Sudden velocity or flow direction changes
 - Flushing
 - Higher than normal demands and fire fighting
 - Valve exercising
 - Tank level change



Next Steps for South Kingstown

- Chlorination station to be constructed at Mautucket Road Tank
 - Design currently under review by RI Dept. of Health
 - Generally consists of precast concrete building, metering pump, day tank, chlorine analyzer, flow meter and SCADA upgrades
- Considering tank mixing system




Summary

- TC hits can be persistent
- Document and save as much data/information occurring before and during the time of the hit for further analysis
- Utilize tools available including SCADA and hydraulic model
- Every system is unique need to carefully review all components to develop a plan



Questions?



Kristen Berger, P.E.

Comprehensive Environmental Inc.

508-281-5160

kberger@ceiengineers.com